

Rev. 1 30-Jan-2000 9-Nov-1999 Page 1 of 1

*Scope: F - Foundation D - Drill & pin S - Shim R - Repair
*Size: S - Under 2 ft. tall M - 2-4 ft. L - 4 -6 ft. XL - Over 6 ft. C - cradle

No vehicle over 5 tons is permitted in the cemetery.

Washington Cemetery Historic Trust
Monument Repair - Phase 5D
Robbins Monument Company

9-Nov-1999

Page 1 of 1

Lot No.	Name	No.	Size*	Scope*	Scope of Work	Repair	Cleaning	Pin Characteristics		
								Number of Pins	Pin Diameter	Pin Length
B-012	Carl	1	C	R (F?)	Repair and clean cradle, clean headstone	150	20	many	0.375	nylon
B-076	Brunner	3	S	F D	Level on new foundations; drill & pin	300	--	3	0.375	5 (nylon)
B-076	Brunner	2	S	F D	Level on new foundations; add bases; drill & pin	150	--	2	0.375	5 (nylon)
C-076	Hahn	1	M	D	Drill, pin, & rejoin on existing base & foundation	150	--	1	0.750	12
C-076	Schilling	1	S	D	Drill, pin, & rejoin on existing base & foundation	150	--	1	0.500	10
C-076	Staeglich	2	S	F D	Level on common foundation; drill & pin	225	--	2	0.500	11
G-062	Fox/White	2	S	D	Drill, pin, & rejoin on existing bases & foundations	175	--	1	0.500	10
Average cost:										
Total Repairs		12		108	Number to be cleaned: 12	1,300	20			
Total, including cleaning							1,320			

*Scope: F - Foundation

D - Drill & pin

S - Shim

R - Repair

*Size: S - Under 2 ft. tall

M - 2-4 ft.

L - 4 -6 ft.

XL - Over 6 ft.

C - cradle

All joints to be secured by pinning and applying adhesive.

No vehicle over 5 tons is permitted in the cemetery.









