

GLENWOOD CEMETERY HISTORIC PRESERVATION FOUNDATION

RODRIGUEZ MONUMENT RESTORATION PROJECTS

(in progress or scheduled)

	Lot Name	Section	Lot No.	Lot Description	Begin Date	End Date	Actual Cost to Date
1.	Mahoney	D	097	SW 1/4	9/19/2005	In progress	84.90
2.	Scheultz	E	095		10/5/2005	In progress	164.90
3.	???	L	???	(repairs for Dick)	10/21/2005	In progress	
4.	Scholibio	WA	257		Scheduled 10/21/2005		
5.	Moon	D	073	600 sf	???		
6.							
7.						Total to date	249.80
8.							
9.							
10.							
11.							


31


marking

069

2 1/2

MONUMENT RESTORATION PROJECT

Priority Status	High (loss) In progress	Lot Purchaser Purchase Date Deed of Perpetuity Contact Last Burial	MAHONEY, Edward 1881 No None 1896	
Section	D			
Lot No.	097			
Description	SW¼			
Work Performed	A small 1883 marker for a child was broken into two pieces and in danger of being lost. The marker was reassembled and set on a new foundation.			
Work To Be Completed	REMOVE FORM; REMOVE OLD FOUNDATION PIECES FROM LOT. RETAKE "AFTER" PHOTO.			




BEFORE: A small 1883 marker for a child had broken into two pieces.



AFTER: The marker has been reassembled and set on a new foundation.

MONUMENT RESTORATION PROJECT

Priority Status	In progress	Lot Purchaser	SCHEULTZ, Edward
Section	E	Purchase Date	1874
Lot No.	095	Deed of Perpetuity	No.
Description	400 s.f.	Contact	None
		Last Burial	1906
Work Performed			
Work To Be Completed	What began as a simple repair to a broken upright marker turned into a discovery. One upright marker had broken in half and the upper portion was lying on the ground and in danger of being lost. The base of the marker was broken and it was decided to level the side-by-side markers on new foundations. During excavation of the marker on the left, a, 6' x 3' marble tablet for two children's graves previously thought to be unmarked was discovered intact about 6" below the surface. It was further discovered that the upright marker was actually a footstone for the two children with a lengthy inscription beginning, "Good bye, our little children . . ." The repairs to the broken upright marker will be made. The marble tablet will be raised and set on a new foundation, and the footstone will be reset. All lot improvements will be cleaned.		



BEFORE: The original purpose was to repair the broken marker on the right.

AFTER:



DURING: A large marble tablet for two graves previously thought to be unmarked was discovered 6" below the surface.

AFTER:


Scholibo, C.F. (#2724)
WA-257
1875
DOP yrs
Last 1965

Artificial-granite 6' H on
55x36" base, 7°E, 2 1/2°N
Whole lot.
2 possible associations




MONUMENT RESTORATION PROJECT

Priority Status	Medium (visibility)	Lot Purchaser	MOON, J. P.
Section	D	Purchase Date	1882
Lot No.	073	Deed of Perpetuity	Yes
Description	600 sf	Contact	None
		Last Burial	1957
Work Performed			
Work To Be Completed	Leveling and resetting of only the marble entrance posts and threshold would improve appearance from the entrance road. The left entrance post is tilting $9\frac{1}{2}^{\circ}$ north and 2° west. The right entrance post is tilting 10° north and 2° east. The threshold is cracked in the middle. Marble cradles are OK. One side of one baby cradle is either missing or buried. The upright marker for the Giesling infant is OK (1° west and 0° north-south). The central monument is marble and approximately 11' tall. It is almost perfectly plumb. The central monument is signed by the manufacturer, J. G. Giesberg & Co., Houston, and one of the burials (1882) is the four-month-old son of J. G. and M. A. Giesberg.		



BEFORE: Restoring only the marble entrance would improve the appearance from the entrance road. The left entrance post is tilting $9\frac{1}{2}^{\circ}$ north and 2° west, and the right post is tilting 10° north and 2° east.

AFTER:



BEFORE: One side of one marble baby cradle is either missing or buried.

AFTER: