


GLENWOOD CEMETERY HISTORIC PRESERVATION FOUNDATION

ESTRADA MONUMENT RESTORATION PROJECTS

(identified, not scheduled)

	Lot Name	Section	Lot No.	Lot Description	Begin Date	End Date	Actual Cost to Date
10.	Lockhart, Anna	C	004		Epoxy marble vase		
11.	Albrecht, Charles	D	024		Inground markers		
12.	Hensley, J. R.	D	029		Epoxy small upright		
13.	Eisen, Charles	D	053	W 1/2	Epoxy small upright		
14.	Dechaumes, S. M.	D	057	ACTIVE CONTACT	Inground markers		
15.	Rooke	D	100	W 1/2	Raise heavy coping		
1.	Schmidt	D	101	W 1/2			
16.	Schmidt, Christine	D	101	W 1/2	2 small cradles and monuments		
17.	Martin, Julia	D	113	ACTIVE CONTACT	Inground markers		
18.	Harris, H. A.	D	136	E 1/2	2 small upright		
9.	Nelson (Peter Wilson)	D	138	SW Corner 10' x 10'			
2.	Cushing	EA	002				
19.	Lucas, James S.	F	008	ACTIVE CONTACT	Inground markers		
20.	Mosehart, H.C.	F	009.5		Inground foundation exposed		
3.	Reiler	F	023				
21.	Reiler, Charles	F	023		Reset footstone		
22.	Terry, J. C.	F	045		Limbs; 2 small upright		
23.	Cage, Julia Ella	F	046	ACTIVE CONTACT	Level lot and med. upright markers		
4.	Schmidt	F	049	N 1/2			
24.	Schmidt, Martin	F	049	N 1/2	Inground; loose urn		
25.	Welch, Julia Hester	F	059.5		Ingrounds foundation exposed		
26.	Blake, E. C.	F	060	ADDRESS; NO NAME	Sinking markers		
5.	Boyce	F	061	800 s.f.			
27.	Boyce, R. P.	F	061	800 s.f.; NAME, NO ADDRESS	Probe for broken markers		
6.	Hutchison	F	064				
28.	Hutchison, O. H.	F	064		Cradles and uprights		
7.	Hearne	F	067	SW 1/4			
29.	Hearne, M. A.	F	067	SW 1/4	Level 2 medium uprights		
30.	Tuffly, B.	F	069		Coping; many small uprights		
31.	Sigel, J. M.	F	070	W 1/2	Stucco coping; small uprights		
32.	Ross, Henrietta	F	078		Ingrounds		
33.	Morse, Mary L.	F	093	SE 1/4	Broken small upright		
8.	Erichson	F	094	W 1/2 (17.5'x20')			
34.	Erichson, Otto	F	094	W 1/2 17.5 x 20	Cradles; level broken uprights		
35.	Barbisch, J. W.	F	136		Straighten/level inground VA		
36.	Frazier (Mellinger)	F	143	Class 40; SPECIAL CARE	Tree root one section coping		
37.							
38.							
39.							

MONUMENT RESTORATION PROJECT

Priority Status	High (loss) Scheduled	Lot Purchaser	LOCKHART, Anna	
Section	C	Purchase Date	1886	
Lot No.	004	Deed of Perpetuity	Yes	
Description	700 s.f.	Contact	None	
Work Performed				
Work To Be Completed	A marble vase approximately 12" tall is resting inside a granite cradle. The vase has cracked into two pieces and should be cleaned and repaired as soon as possible to prevent loss of a piece. There is a long pin in the base of the vase. The central monument on the lot is marble and approximately 6' tall. On its top is a piece approximately the size of the base of the vase. The piece is loose and has shifted. Preliminary investigation suggests it may have been drilled for a pin. Investigate whether the marble vase in the granite cradle is actually the finial of the marble monument. If so, it should be reattached.			



BEFORE: A marble vase approximately 12" tall is resting inside a granite cradle. The vase has cracked into two pieces and should be cleaned and repaired as soon as possible to prevent loss.



BEFORE: There is a long pin in the base of the vase.



BEFORE: The central monument on the lot is marble and approximately 6' tall.



AFTER: The piece on top of the marble monument is loose and has shifted. Investigate whether the marble vase in the granite cradle is actually the finial of the marble monument.

Albrecht, Charles

D-024

1878

DOP Yes


no contact

Last 1958



Hinsley, J.R.
D-029
Purchased 1893

No contact



Reset on base. Level base?

Eisen, Charles

D-053 w/12

DOP 1886

yes DOP

no contact



"Little Marion" Simpson

1886

Dechaumes, S. M.

D-057

1879

No DOP

Contact in Houston



Rooke

DOP 1888

D-100 W1/2

DOP - yes


No contact



Coping, Low markers

MONUMENT RESTORATION PROJECT

Priority Status	Low (visibility)	Lot Purchaser Purchase Date Deed of Perpetuity Contact Last Burial	SCHMIDT, Christine 1881 No None					
Section	D							
Lot No.	101							
Description	W½							
Work Performed	An in-ground granite marker had begun sinking. The marker was raised, leveled and reset on a new foundation							
Work To Be Completed	TWO SMALL CRADLES AND MONUMENTS ON THE LOT NEED REASSEMBLY, RESETTING AND CLEANING.							



BEFORE: An in-ground granite marker had begun sinking.



AFTER: The marker has been raised, leveled and reset on a new foundation

TAKE "BEFORE" PHOTOS OF
CRADLES AND MONUMENTS

BEFORE:

AFTER:

BEFORE:

AFTER:


Martin, Julia

D-113

1913

DOP Yes

Contact: Mrs. Judy Reaves
(Bruce Martin)



Low



Do this at least



Harris, H.A.
D-136 E42
1880
no DOP
no contact,



marker on it. sinking?

Lucas, James S.

~~1888~~ F-008

1888

DOP Yes - Purchased 2001

Contact: Dr. Thos. W. Burke

List 2002



Moshant, H.C.
F-009.5 (400 sf)
1922
DOP Yes
no contact
Last: 1962



Exposed foundation

Reiler, Charles
F-023
1876
DOP no
no contact
Last 1950



Reset
footstone
to prevent
loss.

Reset lot
later.


Terry, J.C.
F-045
1876
DOP No
no contact

Lust 1879



Remove dead limb hanging
over Hamblett.
another limb on S side of tree

Cage, Julia Ella
F-046
1876
DOP Yes
Contact: Catherine Burns
Lust: 1970




Schmidt, Marlin
F-049 N 1/2
1880
DOP Yes
No contact
Lust 1944



This is not
attached +
does not
belong on
this monument

Where does
it go?



Welch, Julia Hunter
F-059.5 (400 sf)
1922
DOP yes
no contact
Lost: 1983



Exposed foundations

Blake, E.C.

F-060

1879

DOP no

Contact address (FL) but no name (Class 80)

Last: 1981

Ch. file for contact name



Markers sinking?

Boyce, R. P.

F-061 (8004)

1880

DOP ho

~~the~~ Contact but no address

Last 1900



Probe for broken markers

Hutchison, O.H.,

F - 064

1876

no DOP

no contact



Hearne, M.A.
F-067 SW 1/4
1932
DOP yrs

No contact
Last: 1938



Truffly, B.

F-069

1870

DOP no
no contact

Last 1977

20 interments - 2 moves

Infants
but no
ashes



Siegel, J. M.
F-070 W 1/2
1879
no DOP
no contact




Coping
pieces
(concrete
beams
set on
brick...)



In G-510
as "SEIGEL"

Ross, Henrietta
F-078
1872
DOP yes
Contact - yes (in AL)



straighten row

Morse, Mary L.

F-093 SE44

1873

no DOP

no contact



Erickson, Otto
F-094 W 1/2 17 1/2 x 20
1872
No DOP
In contact



Barbisch, J.W.

F-136

1919

DOP Yes

No contact

Last: 1969



Straighten & level
VA Marker

Tracy, Yolande M.


F-143

1922 (Geo. Mellinger)

DOP yrs

Last 1999

Special Care



Cut
Tree roots
?