

Washington Cemetery Historic Trust
Monument Repair - Phase 3B
The Monument Company

23-Apr-97

Page 1 of 1

Lot No.	Name	No.	Size*	Scope*	Scope of Work	Cleaning	Repair	Pin Characteristics		
								Number of Pins	Pin Diameter	Hole Depth
A-061	Bender	1	XL	D	Drill, pin, & rejoin on existing base & foundation	25	410			
A-067	Leopold	1	M	F D	Level on new foundation; drill & pin	15	360			
A-069	Lieb	1	L	F D	Level on new foundation; drill & pin	25	560			
A-073	Olive	1	L	S D	Shim on existing foundation; drill & pin	25	270			
A-077	Nolan	1	L	S D	Shim on existing foundation; drill & pin	25	410			
A-101	Wilbushewich	1	XL	D	Drill, pin, & rejoin on existing base & foundation	0	160			
A-124+	Migues	1	M	F D	Level on new foundation; drill & pin	15	345			
B-076	Hykes	1	M	F D	Level on new foundation; drill & pin	15	370			
C-033	Goetzmann	1	XL	D	Drill, pin, & rejoin on existing base & foundation	35	470			
C-115	Leopold	1	M	F D	Level on new foundation; drill & pin	25	535			
C-141	Hanna	1	M	F	Level on new foundation; already pinned	-	200			
P-001	Pender	1	M/C	F D	Level monument and cradle on new foundation; drill & pin	25	435			
Total Repairs		12	Average cost: 377		Number to be cleaned: 11	230	4,525			
Total, including cleaning			396				4,755			

*Scope: F - Foundation

D - Drill & pin

S - Shim

R - Repair

*Size: S - Under 2 ft. tall

M - 2-4 ft.

L - 4 -6 ft.

XL - Over 6 ft.

C - cradle

All joints to be secured by pinning and applying adhesive.

No vehicle over 5 tons is permitted in the cemetery.























