

Washington Cemetery Historic Trust
Monument Repair - Phase 4A
The Monument Company

26-Apr-98

Page 1 of 1

Lot No.	Name	No.	Size*	Scope*	Scope of Work	Cleaning	Repair	Pin Characteristics		
								Number of Pins	Pin Diameter	Pin Length
A-083	Sanders	1	M	S D	Level on new foundation; drill & pin	25	270	1	0.75	16
A-084	Toler	1	XL	D	Drill, pin, & rejoin on existing base & foundation	35	385	3	1,.75,.5	25,18,6
A-088	Collins	1	L	D	Drill, pin, & rejoin on existing base & foundation	15	120	1	1	10
A-114	Branham	1	L	F D	Level on new foundation; drill & pin	25	495	2	1,.625	22,9
A-132	May	1	L	D	Drill, pin, & rejoin on existing base & foundation	25	180	1	1	20
A-133	Stems	1	M	F D	Level on new foundation; drill & pin	25	370	2	0.75	10
A-137	Bell	1	M	S D	Shim on existing foundation; drill & pin	25	270	2	1	22
A-146	Grota	1	L	F D	Level on new foundation; drill & pin	15	270	1	1	21
B-087	Sauer	5	S/M	F D	Level and shim on new foundation; drill & pin (no photos)	70	600	1	0.375	8
C-001	Hoенcke	1	M	D	Drill, pin, & rejoin on existing base & foundation	25	160	2	0.75	17
C-002	Byrne	1	M	F D	Level on new foundation; drill & pin (may be able to shim)	15	370	2	0.625	6
C-010	Dietze	2	L	F D	Level on new foundations; drill & pin	45	930	1	0.75	8
C-010	Dietze	3	M	F D	Level on new foundations; drill & pin	30	520	3	0.625	6
C-022	Selke	1	M	D	Drill, pin, & rejoin on existing base & foundation	25	170	1	0.75	14
C-060	Cook	1	L	F D	Level on new foundation; drill & pin	25	535	1	1	22
C-060	Wise	1	M	F D	Level on new foundation; drill & pin	25	360	2	0.75	10
Total Repairs		23	Average cost: 261		Number to be cleaned: 23		450	6,005		
Total, including cleaning			281				6,455			

*Scope: F - Foundation

D - Drill & pin

S - Shim

R - Repair

*Size: S - Under 2 ft. tall

M - 2-4 ft.

L - 4 -6 ft.

XL - Over 6 ft.

C - cradle

All joints to be secured by pinning and applying adhesive.

No vehicle over 5 tons is permitted in the cemetery.

































