

SAN DIEGO
MARINE
CONSTRUCTION
CO.



Foot of Sampson St.
P. O. Box 751
San Diego
Calif. 92112

Telephone
(714) 239-8051

19 January 1972

STAR OF INDIA and OWNERS

Gentlemen:

San Diego Marine Construction Company is pleased to quote a price of \$27,882.00 to accomplish the following repairs to the "STAR OF INDIA":

1. Tug service to pick up and return vessel to her berth.
2. Necessary drydocking.
3. Clean and sandwash underwater hull.
4. Spot prime with anti-corrosive coating approximately 50% of underwater hull.
5. Coat 100% of underwater hull with anti-fouling coating.
6. Unship rudder for inspection and reinstall. No repairs included.
7. Refit with half round pipe approximately 160 ft. of missing rub rail. Clear heavy scale from between hull and rub rail in four areas and refasten.

Due to the 700 to 800 tons of ballast in the vessel, additional blocking will be required when drydocking to properly distribute this weight.

We thank you very much for the opportunity to submit a quotation.

Sincerely yours,

Arthur J. Yeend
ARTHUR J. YEEND

Vice President - Operations

