

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
W.F.Dunlap	Frame	single	35	16	22	Good	Good	Good	Good	Down to roof	[no damages assessed]

What should be done to make it safe	Remarks
Chimneys should be rebuilt at once	Stovepipe through terra cotta pipes

20 Percy