

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Samuel Lord, Trustee	Brick	Slate	60	45	40	Good	Good	Cracked over openings	Cracked over openings	Cracked to roof	\$1200*

What should be done to make it safe	Remarks
Rebuild chimney tops from roof; anchor building from north to south. Rebuild piazza on south. House needs general repairs.	[none]

* approx. \$ 36,900 today [currency conversion website "Tom's Inflation Calculator"]