

107 East Bay

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
J.W. Oldenbuttel, Store & Dwelling	Brick	Tile	35	25	35	/	/	/	/	/	/

What should be done to make it safe	Remarks
Has been anchored but is not safe; should come down	

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives.