

Owner & Occupant	Material		Dimensions			Condition of Walls			Condition of Chimneys or Flues	Damages by Earthquake (\$)	What should be done to make it safe	Remarks
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East				
H. Oliver Dwelling	Frame	Tin	40	18	25	Good	Good	Good	Down	125	Rebuild chimney's from below ceiling joists. Another kitchen.	[none]

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic  
Charleston Foundation Archives.

27 Tradd