

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
G.I. Cunningham	Brick	Tin	—	—	—	—	—	—	—	—	—

What should be done to make it safe	Remarks
Untenantable, condemned	—

[358-] 360 King St

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives.