

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)	What should be done to make it safe	Remarks
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West				
E.R. Thomas, store	Brick	Tin	60	16	20	Good	Good	Cracked	Good	stovepipe flues	[none recorded]	[nothing recorded]	[nothing recorded]

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives

257 King

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)	What should be done to make it safe	Remarks
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West				
Kohn, Furchgott & Benedict, store	Brick	Tin	125	30	35	Good	Good	Slightly cracked	Good	Good	50	Slight damages. All openings covered with sheet iron, blinds and doors	[none recorded]

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives

259 King

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)	What should be done to make it safe	Remarks
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West				
William Carrington, store & dwelling	Brick	Tin	50	18	33	Division	Good	Badly cracked	Badly cracked	tops down	1200	Rebuild east & west walls from first story. Repair tops of chimneys	Kitchen badly cracked

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives

261 King