

3

M. Roy W. Lewney

In account with

Fort Harrod Motor Co.
INCORPORATED

	Bal brat forward	28	14
8/20	Stop exhaust leaks		50
	Break up engine pan		
	right side		25
	Install new gear in trans		50
	Parts		63
8/29	Replace bars in fit spring	1	00
	Parts	15	26
9/14	Lake miss out of motor		
	Parts	20	35
9/15	Strighten engine pan	50	50
	Leak around motor	1	25
9/22	Put curtain buttons on		
	top bar		50
9/24	Chg. battery	150	25
	Repl. front top bar	1	75
9/22	Parts	2.95	5 23
	Replace sock. in h. ft		25
9/29	Reline trans band	2.00	
	Parts	120	3 20
10/2	Built	20	20
10/20	Repl. Cox controller	35.80	1 15

4566