

4

Harrodsburg, Ky., 2-16 1929

M.

Roy Sewmey

In account with

Fort Harrod Motor Co.
INCORPORATED

26

Bal. brot forward 47 49

9/18 Re-line trans bands ^{2.25}
Repair muffler ⁷⁵ 3 00Parts ⁷⁵ 1 179/20 Repair front spring
Parts ¹⁸⁴ 2 59

9/24 Start car at home 25

9/27 B y Check 3 29

12/4 Take starter loose 25

Replace fender ¹⁵⁰
Straighten run board ¹⁵⁰ 3 001-4801 D Fender ⁶⁰⁰ 6 0010/7 Solder overflow pipe ¹⁰⁰
Tighten rad. rod ⁴⁵ 1 95Tighten steering rods
Appl. trans bands ¹²⁵ 1 70Repair leak in gasoline
Parts ¹⁰⁵ 1 50Replace muffler ⁷⁵Tighten steering
joints ⁴⁵ 1 20

70 10

3 29

Bal.

66 81