


The Audion Control Box also displayed simplicity and efficiency.^{‡‡}



Note, top right, a connection for a tickler coil, suggesting that the IP-501 and its vacuum tube accessory made up a regenerative receiver. Along with its big antennas, that could explain some of the success of NDB.

(08 IX '22 de K6VK) ##

‡ Schematic from: <https://www.navy-radio.com/rcvr-prewar.htm>; hosted by James N. "Nick" England, K4NYW.