HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 12 Oct 89

Survey Team: UNIV OF DC
Members: HERMAN

Video: Reel/Frame
Camera:
Slides: [ ]
B.& W.: [✓]

Name of Property: (if any)

Street Address: 64 HASSELL

Tax Map Number: 458-5-1-51

Current Owner:

DESCRIPTION

Principal Building [✓] Dependency [ ] Other [ ]

No. of Stories: Basement [ ] 1 [ ] 2 [ ] 3 [✓] 4 [ ]
Attic or Half Story [ ]

Material:

Structure: Brick [✓] Wood Frame [ ] Stone [ ] Metal [ ]
Other [ ]:

Surface Covering: Stucco [✓] Wood Siding [ ] Other [ ]:

Roof Covering: Slate [ ] Metal [ ] Tile [ ] Asphalt [ ]
Other [ ]: NOT VISIBLE

Piazza: Foundation: Brick [✓] Stone [ ] Wood [ ]
Other [ ]: STUCCOED

Main Piazza: Brick [ ] Wood [✓] Other [ ]

Roof Covering (if different from main building):

Chimneys: Brick [ ] Brick & Stucco [ ] Stone [ ] Other [ ]
NOT VISIBLE

Comments:
HEXSTYLE, 2-STORY GREEK REVIVAL PORTICO

Address: 64 HASELL Tax Map No.:

Damage Assessment	None	Minor	Major	%
Exterior Features				
Walls: Foundation/Basement	[✓]	[ ]	[ ]	
1st Floor	[✓]	[ ]	[ ]	
2nd Floor	[✓]	[ ]	[ ]	
3rd Floor	[ ]	[ ]	[ ]	
4th Floor	[ ]	[ ]	[ ]	
Attic	[ ]	[ ]	[ ]	
Doors	[ ]	[ ]	[ ]	
Windows	[ ]	[ ]	[ ]	
Shutters				
Piazza/Portico	[✓]	[ ]	[ ]	
Downspouts	[ ]	[ ]	[ ]	
Gutters	[ ]	[ ]	[ ]	
Cornice	[ ]	[ ]	[ ]	
Parapet	[ ]	[✓]	[ ] STRESS CRACKS	
Roof Covering	[ ]	[ ]	[ ]	
Dormers (Number:)	[ ]	[ ]	[ ]	
Chimneys (Number:)	[ ]	[ ]	[ ]	
Other Visible Damage				
Garden Walls/Fences	[ ]	[ ]	[ ]	
Gates	[ ]	[ ]	[ ]	
Walkways/Paving	[ ]	[ ]	[ ]	
Sidewalks	[ ]	[ ]	[ ]	
Trees	[ ]	[ ]	[ ]	
Mechanical	[ ]	[ ]	[ ]	

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 6-27-90

Survey Team: LUND
Members: McCallum

Video: Reel/Frame
Camera:
Slides: [ ]
B.& W.: [ ]

Name of Property: (if any)

Street Address: 64 [redacted] HASELL (REAR)

Tax Map Number: 458-5-1 Lot#51

Current Owner:

DESCRIPTION

Principal Building [ ] Dependency [✓] Other [ ]

No. of Stories: Basement [ ] 1 [ ] 2 [✓] 3 [ ] 4 [ ]
Attic or Half Story [ ] N/A

Material:

Structure: Brick [✓] Wood Frame [ ] Stone [ ] Metal [ ]
Other [ ]:

Surface Covering: Stucco [✓] Wood Siding [ ] Other [ ]:

Roof Covering: Slate [ ] Metal [✓] Tile [ ] Asphalt [ ]
Other [ ]: UNSURE OF THIS

Piazza: Foundation: Brick [✓] Stone [ ] Wood [ ]
Other [ ]:

Main Piazza: Brick [ ] Wood [✓] Other [ ]

Roof Covering (if different from main building): METAL

Chimneys: Brick [ ] Brick & Stucco [ ] Stone [ ] Other [ ]
N/A

Comments: THIS BUILDING IS NOW PART OF A BED AND BREAKFAST.

Address: Tax Map No.:

Damage Assessment	None	Minor	Major	%
Exterior Features				
Walls: Foundation/Basement	[✓]	[ ]	[ ]	
1st Floor	[✓]	[ ]	[ ]	
2nd Floor	[✓]	[ ]	[ ]	
3rd Floor	[ ]	[ ]	[ ]	
4th Floor	[ ]	[ ]	[ ]	
Attic	[ ]	[ ]	[ ]	
Doors	[✓]	[ ]	[ ]	
Windows	[✓]	[ ]	[ ]	
Shutters				
Piazza/Portico	[✓]	[ ]	[ ]	
Downspouts	* [✓]	[ ] Maybe 10%	[ ]	
Gutters	[✓]	[ ]	[ ]	
Cornice	[✓]	[ ]	[ ]	
Parapet	[✓]	[ ]	[ ]	
Roof Covering	[✓]	[ ]	[ ]	
Dormers (Number:)	[ ] N/A	[ ]	[ ]	
Chimneys (Number:)	[ ] N/A	[ ]	[ ]	
Other Visible Damage				
Garden Walls/Fences	[✓]	[ ]	[ ]	
Gates	[✓]	[ ]	[ ]	
Walkways/Paving	[✓]	[ ]	[ ]	
Sidewalks	[✓]	[ ]	[ ]	
Trees	[✓]	[ ]	[ ]	
Mechanical	[✓]	[ ]	[ ]	