



1-96 Smith 1st fl read cistern with lid....



2-96 Smith 1st fl rear doorway lookin...



3-96 Smith 1st fl rear kitchen looking west.jpg



4-96 Smith 1st fl rear looking west to...




5-96 Smith 1st floor rear cistern.jpg



6-96 Smith 2nd f looking NE into room.jpg



7-96 Smith 2nd fl back of door on we...



8-96 Smith 2nd fl bathroom plank wal...



9-96 Smith 2nd fl bathroom plank wall on west.jpg



10-96 Smith 2nd fl detail of area bet...



11-96 Smith 2nd fl detail of door bac...



12-96 Smith 2nd fl detail of door back...



13-96 Smith 2nd fl detail of plank wall...



14-96 Smith 2nd fl detail plank wall.jpg




15-96 Smith 2nd fl east wall with mantel.jpg



16-96 Smith 2nd fl foor leading east t...



17-96 Smith 2nd fl grained room overview looking...



18-96 Smith 2nd fl grained room south wall over...



19-96 Smith 2nd fl graining along north wall.jpg



20-96 Smith 2nd fl graining on door to stair hall lo...



21-96 Smith 2nd fl graining sw corner of room.jpg



22-96 Smith 2nd fl looking east from stair hall.jpg




23-96 Smith 2nd fl looking east note ...



24-96 Smith 2nd fl mantel detail.jpg



25-96 Smith 2nd fl mantel.jpg



26-96 Smith 2nd fl stair landing look...



27-96 Smith 2nd fl, view of top of mantel.jpg



28-96 Smith 3rd fl detail of framing.jpg



29-96 Smith 3rd fl detail of joists with roman num...




30-96 Smith 3rd fl detail showing tool mrks.jpg




31-96 Smith 3rd fl framing in dormer....



32-96 Smith rear dependency with p...



33-96 Smith rear privey.jpg



34-96 Smith St 2nd fl bathroom wood wall on east...



35-96 Smith St 2nd fl graining on south wall of r...



36-96 Smith st 3rd fl Carter Hudgins ...



37-96 Smith St 3rd fl exposed framing.jpg




38-96 Smith stair investigation Carter Hudgins an...



39-96 Smith stair looking up to 3rd fl....



40-96 Smith stair railing detail.jpg



41-96 Smith stair with owner Dan R...



42-96 Smith stair.jpg



43-96 Smith Street 1ft floor front room.jpg



44-96 Smtih 2nd fl graining nw corner of room.jpg