

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
			Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
J.F. Johnson, store & dwelling	Brick	slate	45	20	35	Good	Good	Good	Good	Good	\$375

What should be done to make it safe	Remarks
"Now good."	[none recorded]

28 Hasell