

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Mrs. Drake, Dwelling	Frame	Tin	[NOT RECORDED]			[ALL	GOOD]				

What should be done to make it safe	Remarks
No damage; O.K.	

296 Meeting