

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: Oct. 2, 1989

Video: Reel/Frame

Camera:

Slides: []
B. & W.: []

Survey Team: SOB
Members:

Name of Property: (if any) Sessions Real Estate, Inc. Broad St. Property

Street Address: 65 BROAD ST.

Tax Map Number: 458-9-3-27

Current Owner:

DESCRIPTION

Principal Building Dependency Other

No. of Stories: Basement 1 2 3 4

Attic or Half Story

Material:

Structure: Brick Wood Frame Stone Metal
Other :

Surface Covering: Stucco Wood Siding Other :

Roof Covering: Slate Metal Tile Asphalt
Other :

Piazza: Foundation: Brick Stone Wood
Other :

Main Piazza: Brick Wood Other

Roof Covering (if different from main building):

Chimneys: Brick Brick & Stucco Stone Other

Comments:

Address: 65 Broad

Tax Map No.: 458-9-3-47

Page 2

Damage Assessment	None	Minor	Major	%
Exterior Features				
Walls: Foundation/Basement	[]	[]	[]	
1st Floor	[✓]	[]	[]	
2nd Floor	[✓]	[]	[]	
3rd Floor	[✓]	[]	[]	
4th Floor	[]	[]	[]	
Attic	[]	[]	[]	
Doors	[✓]	[]	[]	
Windows	[]	[✓]	[]	
Shutters				
Piazza/Portico	[]	[]	[]	
Downspouts	[]	[]	[]	
Gutters	[]	[]	[]	
Cornice	[]	[✓]	[]	
Parapet	[]	[]	[]	
Roof Covering	[]	[]	[]	
Dormers (Number: 3)	[]	[]	[]	
Chimneys (Number: 1)	[]	[]	[]	
Other Visible Damage				
Garden Walls/Fences	[]	[]	[]	
Gates	[]	[]	[]	
Walkways/Paving	[]	[]	[]	
Sidewalks	[]	[]	[]	
Trees	[]	[]	[]	
Mechanical	[]	[]	[]	

