

HISTORIC CHARLESTON FOUNDATION  
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10/4/89

Video: Reel/Frame

Camera:

Slides: [ ]

B. & W.: [ ]

Survey Team: Harleston

Members: WILLIE GRAHAM, BOBBY KARR,  
KEN LYNCH, HUGH MCALOON

Name of Property: (if any) Belle France

Street Address: 231 ~~King~~ Street

Tax Map Number: 457-8-1-62

Current Owner:

DESCRIPTION

Principal Building  Dependency [ ] Other [ ]

No. of Stories: Basement [ ] 1 [ ] 2 [ ] 3  4 [ ]

Attic or Half Story [ ]

Material:

Structure: Brick  Wood Frame [ ] Stone [ ] Metal [ ]  
Other [ ]:

Surface Covering: Stucco  Wood Siding [ ] Other [ ]:  
*FACADE*

Roof Covering: Slate [ ] Metal [ ] Tile [ ] Asphalt [ ]  
Other [ ]: N/A

Piazza: Foundation: Brick [ ] Stone [ ] Wood [ ]  
Other [ ]:

Main Piazza: Brick [ ] Wood [ ] Other [ ]

Roof Covering (if different from main building):

Chimneys: Brick  Brick & Stucco [ ] Stone [ ] Other [ ]

Comments:

Address: 231 *King* ~~St.~~ Tax Map No.:

Page 2

Damage Assessment	None	Minor	Major	%
-------------------	------	-------	-------	---

#### Exterior Features

Walls: Foundation/Basement	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
1st Floor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2nd Floor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3rd Floor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4th Floor	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Attic	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Doors	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Windows	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Shutters			
Piazza/Portico	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Downspouts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gutters	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cornice	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Parapet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Roof Covering N/A	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Dormers (Number: 0 )	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Chimneys (Number: 2 )	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Other Visible Damage

Garden Walls/Fences	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gates	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Walkways/Paving	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sidewalks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Trees	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Mechanical	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

