

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 17 JULY 1990

Video: Reel/Frame

Camera:

Slides: [1]

B. & W.: [1]

Survey Team:

Members: MCCALLUM / LUND

Name of Property: (if any)

Street Address: 9 PITT

Tax Map Number: 457-~~458~~
3-4-49

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☐ 1 ☐ 2 ☐ 3 ☒ 4 ☐
Attic or Half Story ☐

Material:

Structure: Brick ☒ Wood Frame ☐ Stone ☐ Metal ☐
Other ☐

Surface Covering: Stucco ☐ Wood Siding ☐ Other ☐

Roof Covering: Slate ☐ Metal ☐ Tile ☐ Asphalt ☒
Other ☐

Piazza: Foundation: Brick ☒ Stone ☐ Wood ☐
Other ☐

Main Piazza: Brick ☒ Wood ☒ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☐ Brick & Stucco ☐ Stone ☐ Other ☐

Comments:

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

\$

Exterior Features

Walls: Foundation/Basement

☒☐☐

1st Floor

☒☐☐

2nd Floor

☒☐☐

3rd Floor

☒☐☐

4th Floor

☐☐☐

Attic

☐☐☐

Doors

☒☐☐

Windows

☒☒☐

Shutters

Piazza/Portico

☒☐☐

Downspouts

☒☐☐

Gutters

☒☐☐

Cornice

☒☐☐

Parapet

☒☐☐

Roof Covering

☐☒☐

Dormers (Number: 0)

☐☐☐

Chimneys (Number: 0)

☐☐☐

Other Visible Damage

Garden Walls/Fences

☒☐☐

Gates

☒☐☐

Walkways/Paving

☒☐☐

Sidewalks

☒☐☐

Trees

☒☐☐

Mechanical

☒☐☐

