

Exterior Survey of King Street Buildings

Date of Survey: 7/25/2005

Address of Property: 231 King

Tax Map Number: 4570801062

Name of Current Occupant(s): Richard James Gallery

Is the Building Under Single Ownership?: ☒ Yes ☐ No

Number of Stories: 3



Use of First Story: ☐ Office ☒ Retail ☐ Restaurant ☐ Bar ☐ Vacant ☐ Other

Use of Upper Stories: ☐ Same as First Floor ☐ Residential ☐ Office ☐ Retail

☐ Restaurant ☐ Bar ☐ Vacant ☐ Other

Number of Bays: 3

Building Shape: Rectangle

Is the Building Connected to Surrounding Buildings?: ☒ Yes ☐ No

Primary Building Material: ☒ Brick ☐ Wood Frame ☐ Stone ☐ Metal ☐ Other

Primary Façade Covering: ☒ Stucco ☐ Wood Siding ☐ Brick ☐ Terra Cotta ☐ Other

Roof Covering: ☒ Not Visible ☐ Slate ☐ Metal ☐ Tile ☐ Asphalt Shingle ☐ Other

Chimneys: ☐ Yes ☒ No – Materials: ☐ Brick ☐ Stucco ☐ Stone ☐ Other

Storefront: ☒ Modern ☐ Restored ☐ Other:

Evidence of Piazza: ☐ Yes ☒ No – If Yes, ☐ Enclosed ☐ Open

Type of Windows on Upper Floors: ☒ Sash ☐ Casement ☐ Dormer – Number of Lights: 9 over 9

Decorative Ironwork on Façade: ☒ Yes ☐ No – Location on Façade/ Description: Anthemion grills

Significant Decorative Elements: Lentils, belt course