

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: July 17 Video: Reel/Frame
Survey Team: CL Camera: []
Members: LM EK Slides: []
E.E.W.: []

Name of Property: (if any)
Street Address: 157 Wentworth
Tax Map Number: 457-3-4-8
Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☐ 1 ☐ 2 ☒ 3 ☐ 4 ☐
Attic or Half Story ☒

Material:

Structure: Brick ☒ Wood Frame ☐ Stone ☐ Metal ☐
Other ☐

Surface Covering: Stucco ☐ Wood Siding ☐ Other ☐

Roof Covering: Slate ☐ Metal ☒ Tile ☐ Asphalt ☐
Other ☐

Piazza: Foundation: Brick ☒ Stone ☐ Wood ☐
Other ☐

Main Piazza: Brick ☐ Wood ☒ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☐ Brick & Stucco ☒ Stone ☐ Other ☐

Comments:

Only tar paper on roof now

40

—