

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Miss M. Valentine, vacant dwelling	Brick	Slate	50	25	38	Parapet down & cracked between openings	Rebuild cracked parts & Parapet	Good	Good	Tops down	\$1,100

What should be done to make it safe	Remarks
Rebuild north and south parapet walls; anchor building north, south, east, and west; rebuild chimneys from below roof and repair and anchor kitchen.	[none recorded]

157 Wentworth St