

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 11/22/89

Video: Reel/Frame

Survey Team:

Camera:

Members: Anom 2

Slides: []

B. & W.: []

Name of Property: (if any) Bob Ellis

Street Address: 332 King

Tax Map Number: 457-4-287

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☐ 1 ☐ 2 ☐ 3 ☒ 4 ☐

Attic or Half Story ☐

Material:

Structure: Brick ☒ Wood Frame ☐ Stone ☐ Metal ☐
Other ☐:

Surface Covering: Stucco ☒ Wood Siding ☐ Other ☐:

Roof Covering: Slate ☐ Metal ☐ Tile ☐ Asphalt ☐
Other ☐: Flat, built up

Piazza: Foundation: Brick ☐ Stone ☐ Wood ☐
Other ☐:

Main Piazza: Brick ☐ Wood ☐ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☐ Brick & Stucco ☐ Stone ☐ Other ☐

Comments: Entire store front ruined roof
100% demolished. S. side of this building
has major horizontal and vertical cracks
in the stucco.

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement

☒☐☐

1st Floor

☐☐☒ 100

2nd Floor

☒☐☒ 40

3rd Floor

☐☐☒ 40

4th Floor

☐☐☐

Attic

☐☐☐

Doors

☐☐☐

Windows

☐☐☒ 80

Shutters

Piazza/Portico

☐☐☐

Downspouts

☐☐☐

Gutters

☐☐☒ 100

Cornice

☒☐☐

Parapet

☒☐☐

Roof Covering

☐☐☒ 100

Dormers (Number: 0)

☒☐☐

Chimneys (Number: 0)

☒☐☐

Other Visible Damage

Garden Walls/Fences

☐☐☐

Gates

☐☐☐

Walkways/Paving

☐☐☐

Sidewalks

☐☐☐

Trees

☐☐☐

Mechanical

☐☐☐