

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10-16-89

Video: Reel/Frame
Camera:

Survey Team: Martha S. Barnes, Ed Tolson,
Members: Laura Haring, Betsy Williams

Slides: [☒]
B. & W.: [☒]

Name of Property: (if any)

Street Address: 12 TRADD ST.

Tax Map Number: ~~156~~ 458-9-3-155

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency [] Other []

No. of Stories: Basement [] 1 [] 2 [] 3 ☒ 4 []

Attic or Half Story []

Material:

Structure: Brick ☒ Wood Frame [] Stone [] Metal []
Other []:

Surface Covering: Stucco [] Wood Siding [] Other []:

Roof Covering: Slate [] Metal [] Tile [] Asphalt []
Other ☒: CAN'T SEE

Piazza: Foundation: Brick [] Stone [] Wood []
Other []:

Main Piazza: Brick [] Wood [] Other []

Roof Covering (if different from main building):

Chimneys: Brick [] Brick & Stucco [] Stone [] Other []

Comments:

Address: 12 Tradd Street Tax Map No.: 155
 10/14/89

458-9-3-

Page 2

Damage Assessment None Minor Major %

Exterior Features

Walls: Foundation/Basement	[✓]	[]	[]	
1st Floor	[✓]	[]	[]	
2nd Floor	[✓]	[]	[]	
3rd Floor	[✓]	[]	[]	
4th Floor	[]	[]	[]	
Attic	[]	[]	[]	
Doors	[✓]	[]	[]	
Windows	[]	[✓]	[]	10 90
Shutters	✓			
Piazza/Portico	[]	[]	[]	
Downspouts	[]	[]	[]	
Gutters	[]	[]	[]	
Cornice	[✓]	[]	[]	
Parapet	[✓]	[]	[]	
Roof Covering	[]	[]	[✓]	50 90 90
Dormers (Number:)	[]	[]	[]	
Chimneys (Number:)	[]	[]	[]	

Other Visible Damage

Garden Walls/Fences	[]	[]	[]
Gates	[]	[]	[]
Walkways/Paving	[]	[]	[]
Sidewalks	[]	[]	[]
Trees	[]	[]	[]
Mechanical	[]	[]	[]

