

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 11.6.89

Video: Reel/Frame

Camera:

Slides: []

B. & W.: []

Survey Team:

Members:

800 #3

Name of Property: (if any)

Street Address: 35 TRADD

Tax Map Number: 458-13-1-12

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☐ 1 ☐ 2 ☒ 3 ☐ 4 ☐

Attic or Half Story ☒

Material:

Structure: Brick ☒ Wood Frame ☐ Stone ☐ Metal ☐
Other ☐:

Surface Covering: Stucco ☒ Wood Siding ☐ Other ☐:

Roof Covering: Slate ☐ Metal ☐ Tile ☒ Asphalt ☐
Other ☐:

Piazza: Foundation: Brick ☐ Stone ☐ Wood ☐
Other ☐:

NX

Main Piazza: Brick ☐ Wood ☐ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☒ Brick & Stucco ☐ Stone ☐ Other ☐

Comments:

Address: 35 TRADD

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

#

Exterior Features

Walls: Foundation/Basement	[]	[]	[]
1st Floor	[✓]	[]	[]
2nd Floor	[✓]	[]	[]
3rd Floor	[]	[]	[]
4th Floor	[]	[]	[]
Attic	[✓]	[]	[]
Doors	[✓]	[]	[]
Windows	[]	[✓]	[] 5%
Shutters	✓		
Piazza/Portico	[]	[]	[]
Downspouts	[✓]	[]	[]
Gutters	[✓]	[]	[]
Cornice	[]	[]	[]
Parapet	[✓]	[]	[]
Roof Covering	[✓]	[]	[]
Dormers (Number: NA)	[]	[]	[]
Chimneys (Number: 2)	[]	[]	[✓]

Other Visible Damage

Garden Walls/Fences	[✓]	[]	[]
Gates	[✓]	[]	[]
Walkways/Paving	[]	[]	[]
Sidewalks	[✓]	[]	[]
Trees	[]	[]	[]
Mechanical	[]	[]	[]