



HISTORIC CHARLESTON FOUNDATION
HURRICANE Hugo DAMAGE ASSESSMENT FORM

Date of Survey: 11/27/89

Survey Team:
Members:

Video: Reel/Frame

Camera:

Slides: []

B. & W.: []

Name of Property: (if any)

Street Address: 23 King

Tax Map Number: 457-16-1-27

Current Owner:

DESCRIPTION

Principal Building Dependency [] Other []

No. of Stories: Basement [] 1 [] 2 3 [] 4 []
Attic or Half Story []

Material:

Structure: Brick [] Wood Frame Stone [] Metal []
Other []:

Surface Covering: Stucco [] Wood Siding Other []:

Roof Covering: Slate [] Metal Tile [] Asphalt []
Other []:

Piazza: Foundation: Brick Stone [] Wood []
Other []:

Main Piazza: Brick [] Wood Other []

Roof Covering (if different from main building):

Chimneys: Brick [] Brick & Stucco [] Stone [] Other []

Comments: Paint damage to NE facade 2nd story
no other visible damage

KING.023.2 Transparency, Slide

Historic Charleston Foundation



Description

Color slide of 23 King Street, taken Jan. 1, 1990. Street elevation, corner view of house. Hurricane Hugo Damage Assessment photograph.