

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Mariner's Church	Brick	Tin	75	30	30	Cracked	Cracked	All down	Badly cracked	Don't see any. Building closed.	100

What should be done to make it safe	Remarks
Anchor north & South walls.	[None]

(note: street # is not identified)

[50] church Street