

HISTORIC CHARLESTON FOUNDATION  
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10/4/89

Video: Reel/Frame  
Camera:

Survey Team:  
Members: SOB

Slides: [ 1 ]  
B. & W.: [ 2 ]

Name of Property: (if any)

Street Address: 50 CHURCH ST

Tax Map Number: 458-13-185

Current Owner:

DESCRIPTION

Principal Building [X] Dependency [ ] Other [ ]

No. of Stories: Basement [X] 1 [ ] 2 [X] 3 [ ] 4 [ ]

Attic or Half Story [ ]

Material:

Structure: Brick [ ] Wood Frame [X] Stone [ ] Metal [ ]  
Other [ ]:

Surface Covering: Stucco [ ] Wood Siding [X] Other [ ]:

Roof Covering: Slate [ ] Metal [X] Tile [ ] Asphalt [ ]  
Other [ ]:

Piazza: Foundation: Brick [X] Stone [ ] Wood [ ]  
Other [ ]:

Main Piazza: Brick [ ] Wood [X] Other [ ]

Roof Covering (if different from main building):

Chimneys: Brick [ ] Brick & Stucco [ ] Stone [ ] Other [ ]  
no vis.

Comments:

## Damage Assessment

None

Minor

Major

%

## Exterior Features

## Walls: Foundation/Basement

## 1st Floor

## 2nd Floor

## 3rd Floor

## 4th Floor

## Attic

## Doors

## Windows

## Shutters

## Piazza/Portico

Screens  
Tipped

## Downspouts

## Gutters

## Cornice

## Parapet

Roof Covering *not vis*

## Dormers (Number: 0)

Chimneys (Number: 0) *not vis*

## Other Visible Damage

## Garden Walls/Fences

## Gates

## Walkways/Paving

## Sidewalks

## Trees

## Mechanical

