

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10/3

Video: Reel/Frame

Survey Team: SOB
Members:

Camera: 4
Slides: [3]
B. & W.: [3]

Name of Property: (if any) Law Offices

Street Address: 129 Broad St.

Tax Map Number: 457-12-4-7

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☐ 1 ☐ 2 ☒ 3 ☐ 4 ☐
Attic or Half Story ☐

Material:

Structure: Brick ☐ Wood Frame ☒ Stone ☐ Metal ☐
Other ☐:

Surface Covering: Stucco ☐ Wood Siding ☐ Other ☐:

Roof Covering: Slate ☐ Metal ☒ Tile ☐ Asphalt ☐
Other ☐:

Piazza: Foundation: Brick ☐ Stone ☐ Wood ☒
Other ☐:

Main Piazza: Brick ☐ Wood ☒ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☐ Brick & Stucco ☒ Stone ☐ Other ☐

Comments:

Address: 129 Broad St. Tax Map No.: 457-12-4-7

Page 2

Damage Assessment None Minor Major %

Exterior Features

Walls: Foundation/Basement

[]

[]

1st Floor

M

[]

2nd Floor

M

[]

3rd Floor

[]

[]

4th Floor

[]

[]

Attic

[]

[]

Doors

M

[]

Windows

M

[]

Shutters

✓

Piazza/Portico

[]

M

Downspouts

[]

[]

Gutters

M

[]

50%

Cornice

[]

[]

Parapet

[]

[]

Roof Covering

[]

M

Dormers (Number:)

[]

[]

Chimneys (Number:)

[]

[]

Other Visible Damage

Garden Walls/Fences

[]

[]

Gates

[]

[]

Walkways/Paving

[]

[]

Sidewalks

M

[]

Trees

[]

[]

Mechanical

[]

[]

