

HISTORIC CHARLESTON FOUNDATION  
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 11.27.89

Video: Reel/Frame

Survey Team: SOTB  
Members:

Camera:

Slides: [ ]

B.& W.: [ ]

Name of Property: (if any)

Street Address: 10 KING

Tax Map Number: 457-16-2-64

Current Owner:

DESCRIPTION

Principal Building  Dependency [ ] Other [ ]

No. of Stories: Basement [ ] 1 [ ] 2 [ ] 3  4 [ ]

Attic or Half Story [ ]

Material:

Structure: Brick [ ] Wood Frame  Stone [ ] Metal [ ]  
Other [ ]:

Surface Covering: Stucco [ ] Wood Siding  Other [ ]:

Roof Covering: Slate [ ] Metal [ ] Tile [ ] Asphalt [ ]  
*flat?* Other [ ]:

Piazza: Foundation: Brick  Stone [ ] Wood [ ]  
Other [ ]:

Main Piazza: Brick [ ] Wood  Other [ ]

Roof Covering (if different from main building):

Chimneys: Brick [ ] Brick & Stucco [ ] Stone [ ] Other [ ]

Comments:

H2O damage - foundation → flood area

Address:

Tax Map No.:

Page 2

Damage Assessment	None	Minor	Major	%
-------------------	------	-------	-------	---

## Exterior Features

Walls: Foundation/Basement	[ ]	[ ]	[X]	H2O
1st Floor	[X]	[ ]	[ ]	
2nd Floor	[X]	[ ]	[ ]	
3rd Floor	[X]	[ ]	[ ]	
4th Floor	[ ]	[ ]	[ ]	
Attic	[ ]	[ ]	[ ]	
Doors	[X]	[ ]	[ ]	
Windows	[X]	[ ]	[ ]	
Shutters	[X]			
Piazza/Portico	[X]	[ ]	[ ]	
Downspouts	[X]	[ ]	[ ]	
Gutters	[X]	[ ]	[ ]	
Cornice	[X]	[ ]	[ ]	
Parapet NA	[ ]	[ ]	[ ]	
Roof Covering	[ ]	[ ]	[ ]	
Dormers (Number: NA)	[ ]	[ ]	[ ]	
Chimneys (Number: 2)	[X]	[ ]	[ ]	

## Other Visible Damage

Garden Walls/Fences	NA	[ ]	[ ]	[ ]
Gates		[ ]	[ ]	[ ]
Walkways/Paving	[X]	[ ]	[ ]	
Sidewalks	[X]	[ ]	[ ]	
Trees	[X]	[ ]	[ ]	
Mechanical	[ ]	[ ]	[ ]	

