

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10-18-89

Video: Reel/Frame

Survey Team: MWC

Camera:

Members:

Slides: [/]

B. & W.: [/]

Name of Property: (if any) Boone House

Street Address: 25 TRADD

Tax Map Number: 458-13-1-40

Current Owner: Dr. B. O. Raschel

DESCRIPTION

Principal Building ☒ Dependency ☒ Other []

No. of Stories: Basement [] 1 [] 2 [] 3 ☒ 4 []

Attic or Half Story ☒

Material:

Structure: Brick ☒ Wood Frame [] Stone [] Metal []
Other []:

Surface Covering: Stucco ☒ Wood Siding [] Other []:

Roof Covering: Slate [] Metal ☒ Tile [] Asphalt ☒
Other []:

Piazza: Foundation: Brick ☒ Stone [] Wood []
Other ☒ can't tell

Main Piazza: Brick [] Wood [] Other []

Roof Covering (if different from main building):

Chimneys: Brick [] Brick & Stucco ☒ Stone [] Other []

Comments:

Address: 25 Tradd

Tax Map No.: 458-13-1-40

Page 2

Damage Assessment None Minor Major %

Exterior Features

Walls: Foundation/Basement	[✓]	[]	[]
1st Floor	[✓]	[]	[]
2nd Floor	[✓]	[]	[]
3rd Floor	[✓]	[]	[]
4th Floor	[✓]	[]	[]
Attic	[✓]	[]	[]
Doors	[✓]	[]	[]
Windows	[✓]	[]	[]
Shutters		✓	
Piazza/Portico	[✓]	[]	[]
Downspouts	[✓]	[]	[]
Gutters	[✓]	[✓]	[] 25
Cornice	[✓]	[]	[]
Parapet	[✓]	[]	[]
Roof Covering	[✓]	[]	[]
Dormers (Number:)	[✓]	[]	[]
Chimneys (Number:)	[✓]	[]	[] 2

Other Visible Damage

Garden Walls/Fences	[✓]	[]	[]
Gates	[✓]	[]	[]
Walkways/Paving	[✓]	[]	[]
Sidewalks	[✓]	[]	[]
Trees	[✓]	[]	[]
Mechanical	[✓]	[]	[]

