

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)	What should be done to make it safe	Remarks
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West				
Mrs. M. Buck Store & Dwelling	Brick	Tin	38	25	40	Cracked	Cracked	Cracked	Cracked	Bad	800	North & south walls should be rebuilt from 1st story. Kitchen in rear, wall out.	[none]

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives.

25 Tradd