

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
			Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
16 Queen John Lutjen	Brick	Tile	30	25	30	Cracked	Down	Cracked	Division cracked	Down	775

What should be done to make it safe	Remarks
Rebuild south wall entire, and top of east & division walls; repair cracks in north wall; rebuild chimneys; rebuild	

kitchen & ~~repair~~ repair building in rear