

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 2 Oct 89

Video: Reel/Frame

Camera:

Slides: [6]
B. & W.: [3]

Survey Team:
Members: 503

Name of Property: (if any)

Street Address: 29 BROAD

Tax Map Number: 453-9-3-125

Current Owner:

DESCRIPTION

Principal Building Dependency Other

No. of Stories: Basement 1 2 3 4
Attic or Half Story

Material:

Structure: Brick Wood Frame Stone Metal
Other :

Surface Covering: Stucco Wood Siding Other :

Roof Covering: Slate Metal Tile Asphalt
Other :

Piazza: Foundation: Brick Stone Wood
Other :

Main Piazza: Brick Wood Other

Roof Covering (if different from main building):

Chimneys: Brick Brick & Stucco Stone Other

Comments:

Address: 29 BROAD

Tax Map No.: 415 8-9-3-125

Page 2

Damage Assessment

None Minor Major

Exterior Features

Walls: Foundation/Basement

1st Floor

2nd Floor

3rd Floor

4th Floor

Attic

Doors

Windows

Shutters

Piazza/Portico

Downspouts

Gutters

Cornice

Parapet

Roof Covering

Dormers (Number: 3)

Chimneys (Number: 1)

Other Visible Damage

Garden Walls/Fences

Gates

Walkways/Paving

Sidewalks

Trees

Mechanical

