

✓

French Quarter

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10/14/89

Video: Reel/Frame
Camera:

Survey Team: USC
Members:

Slides: [2-814]
B. & W.: [2-814]

Name of Property: (if any) CAROLINA PRINTS

Street Address: 188 KING ST.

Tax Map Number: 457-8-2-13

Current Owner:

DESCRIPTION

Principal Building [☒] Dependency [☐] Other [☐]

No. of Stories: Basement [☒] 1 [☐] 2 [☐] 3 [☒] 4 [☐]

Attic or Half Story [☒]

Material:

Structure: Brick [☒] Wood Frame [☐] Stone [☐] Metal [☐]
Other [☐]:

Surface Covering: Stucco [☒] Wood Siding [☐] Other [☐]:

Roof Covering: Slate [☐] Metal [☐] Tile [☐] Asphalt [☐]
Other [☐]:

Piazza: Foundation: Brick [☐] Stone [☐] Wood [☐]
Other [☐]:

Main Piazza: Brick [☐] Wood [☐] Other [☐]

Roof Covering (if different from main building):

Chimneys: Brick [☐] Brick & Stucco [☐] Stone [☐] Other [☐]

Comments:

Address: 188 KING ST.

Tax Map No.: 457-8-2-13

Page 2

| Damage Assessment | None | Minor | Major | % |
|-------------------|------|-------|-------|---|
|-------------------|------|-------|-------|---|

Exterior Features

| | | | |
|----------------------------|---|---|---|
| Walls: Foundation/Basement | [<input checked="" type="checkbox"/>] | [] | [] |
| 1st Floor | [<input checked="" type="checkbox"/>] | [] | [] |
| 2nd Floor | [<input checked="" type="checkbox"/>] | [] | [] |
| 3rd Floor | [<input checked="" type="checkbox"/>] | [] | [] |
| 4th Floor | [<input checked="" type="checkbox"/>] | [] | [] |
| Attic | [<input checked="" type="checkbox"/>] | [] | [] |
| Doors | [<input checked="" type="checkbox"/>] | [] | [] |
| Windows | [] | [<input checked="" type="checkbox"/>] | [] |
| Shutters | | | |
| Piazza/Portico | [<input checked="" type="checkbox"/>] | [] | [] |
| Downspouts | [<input checked="" type="checkbox"/>] | [] | [] |
| Gutters | [<input checked="" type="checkbox"/>] | [] | [] |
| Cornice | [] | [] | [<input checked="" type="checkbox"/>] |
| Parapet | [] | [] | [<input checked="" type="checkbox"/>] |
| Roof Covering | [] | [] | [<input checked="" type="checkbox"/>] |
| Dormers (Number:) | [<input checked="" type="checkbox"/>] | [] | [] |
| Chimneys (Number:) | [<input checked="" type="checkbox"/>] | [] | [] |

Other Visible Damage

| | | | |
|---------------------|-----|-----|-----|
| Garden Walls/Fences | [] | [] | [] |
| Gates | [] | [] | [] |
| Walkways/Paving | [] | [] | [] |
| Sidewalks | [] | [] | [] |
| Trees | [] | [] | [] |
| Mechanical | [] | [] | [] |

