

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
James Weidel, bakery & dwelling	Brick	tile	[not recorded]			Frame	Badly cracked	Division	Good	Twisted	\$525

What should be done to make it safe	Remarks
Rebuild top part south wall rear buildings bakery walls should have attention; rebuild south wall main building from 2d story.	[none recorded]

14 Queen

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives.