

Aiken-Rhett Window, Door & Shutter Totals

Windows

good: 19

fair: 42

poor: 11

conserve: portrait window

TOTAL: 73

Doors

good: 3

fair: 8

poor: 1

Shutters

type 1: existing replacement

(not historic; new fabric)

12 pairs

4 individual

type 2: restored

13 pairs

4 individual

type 3: require restoration

25 pairs

1 individual (on warming kitchen, south window; only one shutter since other removed to accommodate mechanical system)

type 4: missing

5 pairs

OTHER

8 windows with no shutters

1 window to have nothing done

4 pairs in shop for 2nd floor windows

TOTAL: 73

