

Owner & Occupant	Material		Dimensions		Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)					
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West						
German Friendly Society - Dwelling	Brick	Tile	32	16	20	R	E	P	A	I	R	E	D	Good	[None recorded]
What should be done to make it safe	[None recorded]														
Remarks	[None recorded]														

27 Archdale  
(German Fr

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives.