

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 11/22/89

Survey Team:
Members: Anon

Video: Reel/Frame

Camera:

Slides: 3 []

B. & W.: []

Name of Property: (if any)

Street Address: 32 George

Tax Map Number: 457-4-2-4

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☐ 1 ☐ 2 ☐ 3 ☐ 4 ☒

Attic or Half Story ☐

Material:

Structure: Brick ☐ Wood Frame ☒ Stone ☐ Metal ☐
Other ☐

Surface Covering: Stucco ☐ Wood Siding ☐ Other ☐: Asbestos

Roof Covering: Slate ☐ Metal ☐ Tile ☐ Asphalt ☐
Other ☐: Flat built up

Piazza: Foundation: Brick ☒ Stone ☐ Wood ☐
Other ☐

Main Piazza: Brick ☐ Wood ☒ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☒ Brick & Stucco ☐ Stone ☐ Other ☐

Comments: Abandoned apt. building now for sale
suspected major roof and interior damage

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement	☒	☐	☐
1st Floor	☒	☐	☐
2nd Floor	☒	☐	☐
3rd Floor	☒	☐	☐
4th Floor	☒	☐	☐
Attic	☐	☐	☐
Doors	☒	☐	☐
Windows	☐	☒	☐ 50
Shutters	☒		
Piazza/Portico	☒	☐	☐
Downspouts	☐	☒	☐ 50
Gutters	☐	☒	☐ 50
Cornice	☒	☐	☐
Parapet	☒	☐	☐
Roof Covering	☐	☐	☒ 100
Dormers (Number: 0)	☒	☐	☐
Chimneys (Number: 2)	☒	☐	☐

Other Visible Damage

Garden Walls/Fences	☒	☐	☐
Gates	☒	☐	☐
Walkways/Paving	☒	☐	☐
Sidewalks	☒	☐	☐
Trees	☒	☐	☐
Mechanical	☒	☐	☐

