

✓

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10/3/89

Video: Reel/Frame

Camera:

Slides: [2] Roll 7

B. & W.: [4] Roll 8

Survey Team: CHARLESTON

Members: WILLIE GRAHAM, BOBBY KERR
KEN LYNCH, HUGH McALOON

Name of Property: (if any)

Street Address: 109 Rutledge

Tax Map Number: 457 - 3-1 - 103

Current Owner:

DESCRIPTION

Principal Building Dependency [] Other []

No. of Stories: Basement 1 [] 2 [] 3 4 []

Attic or Half Story

Material:

Structure: Brick Wood Frame [] Stone [] Metal []
Other []:

Surface Covering: Stucco Wood Siding [] Other []:

Roof Covering: Slate Metal [] Tile [] Asphalt []
Other []:

Piazza: Foundation: Brick Stone [] Wood []
Other : STUCCO

Main Piazza: Brick [] Wood Other []

Roof Covering (if different from main building):

Chimneys: Brick [] Brick & Stucco Stone [] Other []

Comments:

Address: 109 Rutledge

Tax Map No.: 457-3-1-103

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
1st Floor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2nd Floor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3rd Floor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4th Floor	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Attic	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Doors	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Windows	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Shutters	X		
Piazza/Portico	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Downspouts	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Gutters	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Cornice	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Parapet	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Roof Covering	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Dormers (Number: 0)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Chimneys (Number: 2)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Other Visible Damage

Garden Walls/Fences	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gates	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Walkways/Paving	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sidewalks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Trees	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Mechanical	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

ridge few
shingles

