

Chair # 3 Ditto.

3 B. 8 NK5

condition - Left and right rear legs broken off at apron, Stretcher broken into five segments.

- Back split from top to bottom at middle. One carved side projection broken off.

Broken legs/stretcher:

Task - Glue left leg to existing clean break.

0.5

- reconstruct joint for right leg due to extent of fracture and condition of material.
Attach leg.

4.0

- reassemble stretcher on bench and incorporate into legs at time of reattachment of legs
Rework mitre/tenons as required.

3.0

Broken back

Task - glue split back.

1.0

- clean projection carving of old glue, fit and re-glue

1.0

repair finish as necessary

2.0

$20 \times 11.5 = 230$

11.5