

chair #4 Ditto

4088

condition - stretcher broken off into
three pieces
- carved back projection broken
off.

Broken Stretcher

task. remove attached piece. Clean up
mortise/tenons. Reassemble
and glue in place. 2.0

Broken back

clean projection piece of old
glue, fit and reglue. 1.0

repair finish as necessary 1.0

20X4 = \$80

4.0

chair #5 Ditto

condition - left rear leg broken off
above stretcher attachment.
- Stretcher broken into two
pieces
- back ^{sides} cracked at point where they
form joint to seat frame

Left Rear Leg

task. while break is new repairs
had been made previously.
clean up break area, refit
reglue. 2.0

(cont)