

East Avenue - Maintenance Report

Aug 9, 2010

1. Railey Plot – Lift coping. Coping missing about an 18 inch section on the north side. Small gaps between copings.
2. Dow Plot – Cornerstone displaced on N. Side. Align and raise coping.
3. Glenny Plot – N. side of copings slightly offline.
4. Jones Plot – Raise coping. Coping on west side displaces by bushes.
5. Creighton Plot – Marker for Annie Creighton moved and sitting on the coping. Actual burial spot unknown.
6. Loeffler Plot – Concrete vase broken at the stem.
7. Aiken Plot – Coping damaged in various spots due to weathering.
8. W.P. Cearnal – Vase missing from top of stone.
9. Cecil Madison – rack through tablet that's has been repaired in the past.
10. Mrs. Jennie Whipple – Horizontal and vertical crack through tabled. Horizontal crack has been repaired with concrete.
11. Eliza King – rack through tablet.
12. Mary A. Campbell – Vase missing from top of stone.
13. Mrs E.B. Shanks – Top Half of stone crumbled and 3 pieces lying on the ground. Horizontal crack remaining on top piece. Just a matter of time before it crumbles also.
14. Martin C. Smythe – Marker labeled L.D. sitting next to the Smythe stone. Actual burial spot for L.D. unclear.
15. Annie Eliza Hancock – Rose on top of stone weathered.

16. Lola Hollinger Waters – Large piece missing from the bottom of the stone. If not fixed, the remaining piece will crumble soon.
17. W.A. Miles – Vase missing from top of stone.
18. Rev. Mahlon Day Collins M.D. – Various spider web cracks throughout the stone.
19. Mrs. A. Albertson – Large crack in stone.
20. J.C. Albertson – Small chip out of the back corner of stone.
21. Charles W. Hurley – Level mother and father stones.
22. Marguerite Edith – Crack in tablet.
23. Matteo Grecco – Vase missing from top of the stone.
24. M. Grecco Plot – Cornerstone has large piece broken off, but still present. Cornerstone laying on its side.
25. Isaac H. Oliver – Foot stone coping broken in three places.
26. Robert Rutherford – Two doves on top of stone are both missing their heads.
27. Lewis Plot – Coping slightly displaced. One of the 4 large coping pieces has fallen away from, the plot and is sunk in the mud and lying on its side.
28. De George Plot – Coping slightly displaced and sunk. A cornerstone is displaced.
29. **Emma C. Barnes** – Stone needs to be leveled. Cross on top of stone is unstable and could easily fall off and break.
30. M.D. Chiara Plot – Cornerstone slightly displaced.
31. T.J. M. Richardson – Two small tablets stones, one reading mother and one father are leaning against the main stone. They need to be reset.
32. Norbert Choucrown and Will L. McLendon – Marble needs repair. Half of face missing on left angel.
33. Bergman Plot – One of the cornerstones does not match the rest.
34. **Gracie Despos** – Grave is on the woods and covered with compost. Area surrounding the grave needs to be cleared and the compost removed. Various other small markers were lying in

the woods. They appear to have been thrown there. I gathered them and put them on the edge of the woods close to the Despos marker. Two of the stoned have initials carved in them.

35. Gordon Plot – Brick and concrete coping needs to be redone.

36. Brick surrounding East Avenue – Brick is broken right where the brick starts by the entrance of the cemetery.