

Maintenance Report; Section D-2

Aug 23, 2010

1. S. V. Wheat - Pot missing from top of stone.
2. Dell Schevalm - Horizontal crack in stone.
3. Eddie A. Mather – Pot missing from top of stone.
4. Jacob Eckel – Marble vase near base of stone missing.
5. Bertha Veith – Chips out of the marble on top of marker and base stone.
6. Mrs. Mary Borgstedt – Horizontal crack in stone.
7. William Borgstadt – Nob on pot, which is on the top of the marker is broken off.
8. Asa, Charlie, and Ann Jarmon – Coping is mostly buried and broken in some places.
9. Ruthie and Minnie Mahoney – Lamb heads broken off and missing.
10. Frank Lawrence – Lamb head broken off and missing.
11. Mrs. Bohdie – Horizontal crack in through stone.
12. Edward Hermann – Two horizontal cracks through pillar stone.
13. Massie Lewis – Horizontal crack through stone. Has been repaired. Foot coping in bad shape.
14. Mary Mckee – One large vertical crack forming. Two large pieces broken off of the bottom left corner, but still present.
15. Lucy Taylor – Horizontal crack through stone, but has been repaired.
16. James Geraud – Vase missing from foot coping.
17. Charlotte Ebert – Various broken pieces and coping.
18. Charlotte and Herman Holtkamp – Pot missing from the top of stone.
19. Belle Bennice – Foot coping badly weathered.
20. Max Seelhorst – Large horizontal crack through stone.
21. Abram Mabie - Nob on pot, which is on the top of the marker is broken off.
22. George Koehl - Nob on pot, which is on the top of the marker is broken off.
23. Wilmer D. Hyde – Crack through stone but has been repaired.
24. W.C. Anders – Marble slab in front of stone is partly buried. Coping is in bad shape.
25. Meyer Plot – Stone labeled E.M. needs to be straightened. Large chip out of the Father stone. Various breaks in coping.
26. Samuel Smith Hudson and Martha Jarvis Hudson – Large chunk missing from marble base. Two nearby tablet stones have been broken off at ground level and are missing.
27. Octavia Little – There is a stone about 10 feet behind this one that is broken in half and the broken pieces are lying on the ground. The broken marker is concrete.
28. Edward Herzog – Vase on foot coping broken off and missing.

29. Ballard and McKee plot – Brick and concrete coping in bad shape and broken.
30. Heffernan Plot – Coping is out of line and needs to be straitened.
31. C.B. William plot – Coping needs to be realigned. Various breaks in coping.
32. Jacob Eckel Plot – Realign coping and cornerstones.
33. S.V. Wheat Plot – Various breaks in coping.
34. Hite Plot – Tree roots have lifted and moved some of the marble markers.
35. J. Augusta Lieck – Lamb head is missing from marker.
36. Asa Jarmon – Stone chipped in two places and a crack is forming.
37. Brick surrounding coping – Brick is broken or cracked in three places on the west side of the section from tree roots.