

Martha —

GLENWOOD CEMETERY, INC.

WORK ORDER

Date:

11-21-07

Time:

2 pm

Assigned to:

By:

Lma

Section:

E

Lot No./Description:

Marker(s) on Lot:

74

name

W.T. Mathews 1872

Work To Be Performed:

headstone fallen
& broken

Lot Owner:

Brady Lot

Requested by:

needs repair +
resetting

Billing Address:

Lew & Sidney Brown
936 597 6838

Headstone is
broken at bottom.
strip of marble
is broken which
fits in the inset
portion of the
base. all
marble.

ID

(Employee)

(Time spent)

(Time spent)

h: _____

h: _____

: _____

: _____

: _____

: _____

: _____

nature)

e work is complete.

Maryann
Open a work order
for the Brady ~~Hunt~~
Lot in E 74 ~~or E 57~~?

Headstone has fallen &
~~Monument~~ is broken - needs repair
& resetting.

Lew & Sidney Brown

936-597-6838 - family
might pay - do not know