

Glenwood



Cemetery

<u>MemberID</u>	<u>Section</u>	<u>LotNumber</u>	<u>LotDescription</u>	<u>LotSqFt</u>	<u>Purchase Date</u>
3,172	F-1	030	N/A	400	9/1/1876

Lot Owner:

Spouse or Contact Information:

Name: Mrs. M. V. Waldo

Address:

Houston, TX 99999

Phone 1:

Phone 2:

Name:

Remarks:

Interments:


<u>ID</u>	<u>Name</u>	<u>Marker</u>	<u>Burial Date</u>
12,913	Milton O. Waldo <i>Remarks:</i>	Yes	1/10/1867
12,912	Matilda O. Waldo <i>Remarks:</i>	Yes	1/21/1868
12,908	Jedediah Waldo <i>Remarks:</i>	Yes	11/9/1896
12,909	Mrs. Mary Virginia Gentry Waldo <i>Remarks:</i>	Yes	1/2/1922
12,907	Gentry & Katherine Waldo <i>Remarks:</i> Ashes-Father & Daughter	Yes	8/24/1934
12,915	Wilmer Waldo <i>Remarks:</i>	Yes	12/10/1962
12,910	Lula Waldo <i>Remarks:</i>	Yes	12/3/1963
12,911	Mary Waldo <i>Remarks:</i>	Yes	12/9/1965
12,914	Virginia Waldo <i>Remarks:</i>	Yes	9/11/1974

3/29/2010 12:38:55PM

Total Interments: 9

Waldo Plot - Obelisk repair needs to be lightened after cleaning

Glenwood



Cemetery

<u>MemberID</u>	<u>Section</u>	<u>LotNumber</u>	<u>LotDescription</u>	<u>LotSqFt</u>	<u>Purchase Date</u>
3,172	F-1	030		400	9/1/1876

Lot Owner:

Spouse or Contact Information:

Name: Mrs. M. V. Waldo

Address:

Houston, TX 99999

Phone 1:

Phone 2:

Name:

Remarks:


Interments:

<u>ID</u>	<u>Name</u>	<u>Marker</u>	<u>Burial Date</u>
12,913	Milton O. Waldo <i>Remarks:</i>	Yes	1/10/1867
12,912	Matilda O. Waldo <i>Remarks:</i>	Yes	1/21/1868
12,908	Jedediah Waldo <i>Remarks:</i>	Yes	11/9/1896
12,909	Mrs. Mary Virginia Gentry Waldo <i>Remarks:</i>	Yes	1/2/1922
12,907	Gentry & Katherine Waldo <i>Remarks:</i> Ashes-Father & Daughter	Yes	8/24/1934
12,915	Wilmer Waldo <i>Remarks:</i>	Yes	12/10/1962
12,910	Lula Waldo <i>Remarks:</i>	Yes	12/3/1963
12,911	Mary Waldo <i>Remarks:</i>	Yes	12/9/1965
12,914	Virginia Waldo <i>Remarks:</i>	Yes	9/11/1974


10/7/2010 3:16:05PM

Total Interments: 9

Waldo Monument F-1, 030 (Before and After)









BEFORE




AFTER



P-1, 030 Mrs. M.V. Waldo
Crack in monument repaired by Eric Kaposta



III





Before / During



After

Waldo



3172 F-1, 030
Mrs. m.v. Waldo