

TIME SHEET

GLENWOOD CEMETERY

PROJECT ON section I Lote Repair.

01- 26, 2006

Employee	In	Out	Hours Worked	Worked Performed
Mario Rodriguez	8:Am.	5:pm.	8	
Ishmael Ramos	8:Am.	5:pm.	8	lote Repair ON section I
Teofilo Aguilar				
				Job. is DONE.
TOTAL HOURS				

Equipment Used	Hours Used	Worked Performed
no		

Materials Used	Quantity Used
8 Bag concrete mix - 80 pounds	
8 MORTAR mix - 80 pounds	

Completed by _____, _____, 2006

Mario Rodriguez

TIME SHEET

GLENWOOD CEMETERY

PROJECT LOT REPAIR ON SECTION I
03-15, 2006

Employee	In	Out	Hours Worked	Worked Performed
Mario Rodriguez	8:Am.	5:pm.	8	LOT REPAIR 8:Am. To 3:pm. is DONE.
Robert Tovar	8:Am.	5:pm.	8	
Teofilo Aguilar				
Florencio Solano				CURVE DAMAGE ON F
				REPAIR. DONE.
				FROM: 3:pm. To 5:pm.
TOTAL HOURS				

Equipment Used	Hours Used	Worked Performed

Materials Used	Quantity Used
8 Bag MORTAR mix. 80:POUND.	

Completed by _____, _____, 2006
Mario Rodriguez

TIME SHEET

GLENWOOD CEMETERY

PROJECT Section I South Perimeter wall

8-03, 2006

Employee	In	Out	Hours Worked	Worked Performed
Mario Rodriguez	8:Am.	5:pm.	8	
Robert Tovar				pressure washer
Teofilo Aguilar				
TOTAL HOURS				

Equipment Used	Hours Used	Worked Performed
pressure washer Machine	8	

Materials Used	Quantity Used

Completed by _____, _____, 2006

Mario Rodriguez

TIME SHEET
GLENWOOD CEMETERY

PROJECT Ambros ON "E"
05 - 22, 2006

Employee	In	Out	Hours Worked	Worked Performed
Mario Rodriguez	8:Am.	5:pm.	8	
Robert Tovar	8:Am.	5:pm.	8	RESET STONES. 3 inch - To RIGHT
Teofilo Aguilar				Job DONE.
TOTAL HOURS				

Equipment Used	Hours Used	Worked Performed
no		

Materials Used	Quantity Used
10 Bag concrete mix - 80 pound.	

Completed by _____, _____, 2006
 Mario Rodriguez

TIME SHEET

GLENWOOD CEMETERY

PROJECT

AMBRUS Job.

06-07

, 2006

*Ligustrum in ✓
Remove for soldier
pin wale*

Employee	In	Out	Hours Worked	Worked Performed
Mario Rodriguez	8:Am.	5:pm.	8	
Robert Tovar				pull of Threes is Total. AND CLEAN UP.
Teofilo Aguilar	8:Am.	5:pm.	8	
				DONE.
TOTAL HOURS				

Equipment Used	Hours Used	Worked Performed
Yellow Tractor.	P	

Materials Used	Quantity Used
NO.	

Completed by _____, _____, 2006

Mario Rodriguez

TIME SHEET

GLENWOOD CEMETERY

PROJECT ON I
7-10, 2006

Employee	In	Out	Hours Worked	Worked Performed
Mario Rodriguez	8:Am.	5:pm.	8	
Robert Tovar	8:Am.	5:pm.	8	CURVE REPAIR. (Berke
Teofilo Aguilar				damage)
				job done
TOTAL HOURS				

Equipment Used	Hours Used	Worked Performed
NO		

Materials Used	Quantity Used
6-Bag MORTAR mix - 80 pound.	

Completed by _____, _____, 2006
Mario Rodriguez